

Field/Material Report

Report #: 90378

A.A.R. Testing Laboratory, Inc. 7126 180th Ave.N.E., Park 180, Suite C101, Redmond, WA 98052
Phone 425.881.5812 Fax 425.881.5441

Client Name: Juanita Farmhouse Cottages LLC

Project Number: 16-150

Contact: Kim Saunders

Permit # BMI 15-06785

Client Address: 20037 94th Ave. N.E.
Bothell, WA 98011

Project Name: Juanita Farmhouse Cottages
Address: 12652 94th Ave. N.E.

Date: 4/15/2016

Supplier:	CalPortland	Air Temperature:	55 F	
Material Data:	Concrete	Concrete Temperature:	64 F	ASTM C 1064
Plant Number:	260	Air Content:	%	ASTM C 231
Mix Number:	63065	Slump:	5 "	ASTM C 143
Truck Number:	7347	Time Sampled:	10:30:00 AM	
Ticket Number:	1358631	Added Water:	10	ByWhom: Contractor
Number of Samples:	5	Air Entrainment (oz/yard):		
Yards placed:	10/70	Admixtures (oz/yard):	WRDA64	15
Design Strength:	5000			

Inspection Performed: Reinforced Concrete

Location: Water detention vault - footings and slab on grade

Grid Lines:

Remarks: Resteel is placed in conformance with the details on page SD4 of plans. Concrete was placed by boom pump and consolidated with vibrator.

☒ Conforming to approved plans

Inspector: Panov, Krasimir

2nd Inspector:

3rd Inspector:

Samples Tested in Accordance with ASTM: C 1231 C 31 C 172 C 39

Sample ID	Test Date	Age	Size	Area	Set #	Total Load	PSI	Method	Fracture Type
1603936	4/22/2016	7	4 X 8	12.56	1/1	58120	4630	C 1231	Cone

Distribution:

☒ Client

☒ Contractor

☐ Owner

Date Mailed:

☒ Municipality

☐ Engineer

☐ Architect

Tested By: Chris London

☐ Distribute Other

Reviewed: Mike Blackwell

All tests in accordance with the requirements of ASTM C 31 for casting and curing concrete specimens in the field excluding Section 10.1.2 (required use of a maximum-minimum thermometer). All reports are considered confidential and are the property of the client and A.A.R. Testing Laboratory, Inc. Reproduction except in full, without the written consent of A.A.R. Testing Laboratory is strictly forbidden.

Field Report

Report #: 66644

**A.A.R. Testing Laboratory, Inc. 7126 180th Ave.N.E., Park 180, Suite C101, Redmond, WA 98052
Phone 425.881.5812 Fax 425.881.5441**

Client: Juanita Farmhouse Cottages LLC

20037 94th Ave. N.E.

Bothell, WA 98011

Project Number: 16-150

Permit #: BMF 15-06785

Project Name: Juanita Farmhouse Cottages

Contact: Kim Saunders

Address: 12652 94th Ave. N.E.

Inspection Performed: Resteel

Date: 4/20/2016

Time:

Temperature:

Water detention vault-walls:

Rebar is placed in conformance with details: 2/SD2, 3, 16, 17, 18, 19/SD4 except for:

1. #6 verticals 2'6" at 18" on center top of walls in closure - typical
2. The 2 #5 horizontal at top of walls - typical
3. #6 at 18" on center into the footing top of wall on line 1 as per 2/SD2

Work is in progress on the above mentioned (3) items to be reinspected before concrete placement.

Distribution:

- | | |
|---|---|
| <input checked="" type="checkbox"/> Distribute Client | <input checked="" type="checkbox"/> Distribute Contractor |
| <input type="checkbox"/> Distribute Engineer | <input type="checkbox"/> Distribute Owner |
| <input checked="" type="checkbox"/> Distribute Municipality | <input type="checkbox"/> Distribute Other |
| <input type="checkbox"/> Distribute Architect | <input type="checkbox"/> Distribute Other |

Inspector: Panov, Krasimir

Reviewed by: Michele Guerrini

All reports are considered confidential and are the property of the client and A.A.R. Testing Laboratory, Inc.
Reproduction except in full without the written consent of A.A.R. Testing is strictly forbidden